

SAFETY CERTIFICATE


TO WHOM IT MAY CONCERN

It is certified that the Air Force buildings in which Kendriya Vidyalaya Mullanpur Garibdass is operating in well maintained by school authorities and the building is structurally safe, provided with potable water, electric supply and sanitary facilities. However, at certain places of class rooms/corridor it is noticed that roofing sheets are broken/cracked needs to be replaced to avoid any damage/leakage.

I have inspected the buildings on ... 07.06.2021

Date: 16 Jun 2021

Place: Chandigarh


D K Vishwakarma
(AE Civil)
AGE B/R (P) Chd

COUNTER SIGNATURE BY CHAIRMAN VMC


(अरविन्द कुमार / Arvind Kumar)
ग्रुप कैप्टन / Gp Capt
कमान अधिकारी / Commanding Officer
2224 स्क्वाड्रन वा. से. / 2224 Sqn, AF